

Nº 8912

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED

DATE INSPECTED \_\_\_\_\_ IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM \_\_\_\_\_

HOUSE NO. \_\_\_\_\_ DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
SIZE OF PIPE USED \_\_\_\_\_ CURB LINE AND DEPTH \_\_\_\_\_

WAS LATERAL AT CURB? \_\_\_\_\_

WAS ATTACHED TO MAIN \_\_\_\_\_ NAME OF CONTRACTOR \_\_\_\_\_

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

*No Inspection*

SIGNED \_\_\_\_\_ FILED AT ENGINEER'S OFFICE \_\_\_\_\_  
Inspector for City

REMARKS \_\_\_\_\_

CUT-OFF

Nº 8912

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
PERMIT TO TAP SEWER

MASSILLON, OHIO,

Feb. 13

RECEIVED OF

East 30 Excavating

FEE OF \$ 5.

FOR WHICH PERMISSION IS GRANTED

A. Cameron

CUT-OFF

TO-TAP

Sanitary

SEWER ON THE

West

OF

3rd St. S.W.

AVE.

ST. TYPE OF STREET

Brick

THE PREMISES BEING LOT NO.

171

HOUSE NO.

53

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

East 30

**Note: This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.**