FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 8917 AND SIGNED WHEN RETURNED

HOUSE NO. 406 SIZE OF PIPE USED 6" WAS LATERAL AT SURB? Ves	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CORRELLINE AND DEPTH Prop
WAS ATTACHED TO MAIN NO	NAME OF CONTRACTOR THAT IS
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	
Tenere and the second s	8' 32'0p
SIGNED Vation Inspector for City	FILED AT ENGINEER OFFICE

Nº 8917

OFFICE OF THE DIRECTOR OF PUBLIC SEI PERMIT TO TAP SEWER

	MASSILLON, OHIO,	419
RECEIVED OF LUAL NO.	51. 638.00.00	FEE OF \$ 2 2
FOR WHICH PERMISSION IS GRANTED	1 Westman	·
TO TAP Same Say SI		
ог AVE. т	YPE OF STREET Care A	
THE PREMISES BEING LOT NO. 13550	, HOUSE NO	6
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO		
NAME OF CONTRACTOR Township		
	_	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.