

N^o 8920FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

4-19-76

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED

WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

SIGNED

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Operator @ PLANT didn't Tell Inspector. Sewer installed &
UP Before Inspector Arrived Two Days Later

Nº 8920

OFFICE OF THE DIRECTOR OF PUBLIC SEW
PERMIT TO TAP SEWER

MASSILLON, OHIO, *April 6*

RECEIVED OF

Paul Kananichy

FEE OF \$ *2.50*

FOR WHICH PERMISSION IS GRANTED

Paul Kananichy

TO TAP

Sanitary

SEWER ON THE

South

OF

Lawrence Dr. N.E.

AVE.
ST. TYPE OF STREET

Uppland

THE PREMISES BEING LOT NO.

13669

HOUSE NO.

2527

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Reece

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.