

Nº 8927

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR  
AND SIGNED WHEN RETURNED**

DATE INSPECTED June 17 76

IF SO HOW AND LOCATION FROM  
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1051

SIZE OF PIPE USED 6

DISTANCE FROM FIRST MANHOLE  
DOWN STREAM TO DITCH AT  
CURB LINE AND DEPTH


WAS LATERAL AT CURB? 16 feet behind curb

Gray Bagg

WAS ATTACHED TO MAIN yes no

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



S W Z  
E

SIGNED

Jesse N Lewis

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 8927

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE  
PERMIT TO TAP SEWER

MASSILLON, OHIO, *April 27*

RECEIVED OF *Erving Reas*

FEE OF \$ *25*

FOR WHICH PERMISSION IS GRANTED *Erving Reas*

TO TAP *Sanitary*

SEWER ON THE *West*

OF *Adams Hill Cir, W.E.*

AVE.

ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *13712*

HOUSE NO. *1051*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND  
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Malavite*

**Note: This permit covers work outside of building only. Any work  
walls of building is subject to Massillon Board of Health Regulations.**