Nº 8931

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 5-3-76 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2429  DISTANCE FROM FIRST MANHOLE  DOWN STREAM TO DITCH AT 22 WEST OF MY 1/0 PT  WAS LATERAL AT QUIRB? YES Prop
WAS ATTACHED TO MAIN 110 NAME OF CONTRACTOR 17. GEYSTENUSTAGEY
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.
SIGNED J. Jathoun FILED AT ENGINEER'S OFFICE
Inspector for City

**№** 8931

## OFFICE OF THE DIRECTOR OF PUBLIC SEE PERMIT TO TAP SEWER

	MASSILLON, OHIO,	april	I 9
RECEIVED OF Sentimetry			FEE OF \$
FOR WHICH PERMISSION IS GRANTED Law L	henren		
TO TAP Sometary SE		South	
or bagines di. 71.4. AVE. ST. T			
THE PREMISES BEING LOT NO. 13687		L <sup>7</sup>	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N			
OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR	/ 		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.