8934

 $N^{\underline{o}}$

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED $5 - 6 - 76$ HOUSE NO. 131	IF SO HOW AND LOCATION FROM TAPPED ON 30" Trunk of
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? NO	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR // DEVBAUM
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	
	JORE PART
	GOP L
W	75 66
4 4-1	3011 Trune 14 1
SIGNED C Calling inspector for City	FILED AT ENGINEER'S OFFICE 3/4
mapacion for Oity	••

№ 8934

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, 77/ 6	
RECEIVED OF Bladeline dum		7 5.4 E
FOR WHICH PERMISSION IS GRANTED 1.		4
TO TAP	JER ON THE Sacth	
OF transtar Site. AVE. ST. TY	DE CE STREET Stand Lingue	ئے۔۔۔
THE PREMISES BEING LOT NO. 1002	f	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO		
OF THE DEPARTMENT OF PUBLIC SERVICE.		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.