## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

8938

DATE INSPECTED My 15 76	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO		
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	·
WAS LATERAL AT CURB?		1
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR	
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.	
at	Casoment	
SIGNED.	FILED AT ENGINEER'S OFFICE	
Inspector for City		
REMARKS		

CUT-OF

**№** 18938

OF THE DEPARTMENT OF PUBLIC SERVICE.

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO	, 7/1/ 1ª	/ · · ·
RECEIVED OF at 30 Warehair	eg Gr.	0	FEE OF S
EOD WHICH BEDMISSION IS CRANTED 77/443	Care Suran	irlg	
CUT-OFF, -	WER ON THE	Courte	,
of Highward St. W. St. T.		Un Fal	ia C
THE PREMISES BEING LOT NO. 910 F	, но	USE NO. 33	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N	O. 19-1971 DULY	PASSED BY THE C	TY COUNCIL, AND F

NAME OF CONTRACTOR\_\_\_\_\_\_\_

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.