FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

 $N_{\bar{0}}$

8939

DATE INSPECTED 252/7, 197	16 SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
House No	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	the state of the s
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WA	ALL OF BUILDING SERVED.
clo	Deral lateral jain
SIGNED	FILED AT ENGINEER'S OFFICE
Inspector for City	
REMARKS	

Nº 8939

OFFICE OF THE DIRECTOR OF PUBLIC SEF PERMIT TO TAP SEWER

MA	SSILLON. OHIO.	May 17	<u> </u>
RECEIVED OF BLAZE Executing	Co-	U	FEE OF S
FOR WHICH PERMISSION IS GRANTED Dicke	aung		
TO TAP SEWER	CN THE	Mut	
of Chiff M. W. AVE. ST. TYPE C		Was En	in C
THE PREMISES BEING LOT NO. 9502	, Hous	1 100	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 15	9-1971 DULY P	ASSED BY THE CIT	Y COUNCIL, AND F
OF THE DEPARTMENT OF PUBLIC SERVICE.			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.