Nº 8951

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	DISTANCE FROM FIRST MANHOLE
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
2.2	the second secon
•	
SIGNED	FILED AT ENGINEER'S OFFIÇE
Inspector for City	
REMARKS	

Nº 8951

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

RECEIVED OF A. Diana lows FEE OF sal	- a. D. Diana Jans
Of Bell (Rith Cupail)	Ir * ret Ur \$1 ret Ur \$1
OR WHICH PERMISSION IS GRANTED	SSION IS GRANTED Of Bell (Ruth Cupari)
O TAP Saintary SEWER ON THE West	Tary SEWER ON THE West
F 11th St. 71.6. AVE. ST. TYPE OF STREET Hand luface	St. 71.6. AVE. ST. TYPE CF STREET And lugare
HE PREMISES BEING LOT NO. 9614 , HOUSE NO. 577	•
ORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND	E IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND F
AME OF CONTRACTOR Diana	Vina.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.