

19-49

N^o 8956


**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED 7/19/76IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM6" LATERAL ... 145' FROM MANHOLEHOUSE NO. 2463 VALLEYWOODSIZE OF PIPE USED 6"DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH145' FROM MANHOLE / DITCH 7 1/2' AT CURBWAS LATERAL AT CURB? YESWAS ATTACHED TO MAIN YES

NAME OF CONTRACTOR

MALINITE

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

DITCH: 7 1/2' AT CURB7 1/4' ± AT HOUSE

SIGNED

Ryan W. Lash

Inspector for City

FILED AT ENGINEER'S OFFICE

7/19/76

REMARKS

TAPPED EXISTING LATERAL 16' BEHIND CURB(PIPE RUNS 52' FROM CURB TO HOUSE)

Nº 8956

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, June 28, 1976
RECEIVED OF Creature Structures FEE OF \$ 25.00
FOR WHICH PERMISSION IS GRANTED Creature Structures
TO TAP Sanitary SEWER ON THE North SIDE
OF Ballenger Road No. 71.6 AVE. ST. TYPE OF STREET City & Sub
Logwood Ln 71.6
THE PREMISES BEING LOT NO. 13648, HOUSE NO. 2440 2463
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RULES
OF THE DEPARTMENT OF PUBLIC SERVICE.
NAME OF CONTRACTOR Melanite

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.