Nº 8963

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED Wy 3 76	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 3/6	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	NAME OF CONTRACTOR Carl Clean
WAS ATTACHED TO MAIN	
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
Enty bet 9 fe	IL OF BUILDING SERVED.
32 feet of sip at	8 feet deep
Kender	
7/8	
SIGNED	FILED AT ENGINEER'S OFFICE
Inspector for City	
REMARKS	·

Nº 8963

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OH	10. 11.269	r. <i>I</i>
RECEIVED OF Samus	Llick		EEE DE 525.
FOR WHICH PERMISSION IS GRANTED a MU	Male	<u> </u>	
TO TAB Samilary SE	WER ON THE	<u> </u>	actif.
of Lake an. VI.6. AVE. T. T.			
THE PREMISES BEING LOT NO. 10985			
· · · · · · · · · · · · · · · · · · ·	,		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE N	D. 19-1971 DUL	Y PASSED BY	THE CITY COUNCIL, AND F
OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR & al Shick			
NAME OF CONTRACTOR & STATE OF THE STATE OF T			

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.