FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

№ 8978

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAINSHOW BY DIAGRAM RELATION OF LATERAL TO WAL	NAME OF CONTRACTOR
SIGNEDInspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 8978

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON,	оню,	7.49.	31	
RECEIVED OF Binn Ex					s = - !
FOR WHICH PERMISSION IS GRANTED					
CUT-OFF January	SEWER ON THE	1 7%	المستند الماريخ والاس		
or 13 # II I & E-			g*3	i.	
THE PREMISES BEING LOT NO. 2762					ad along data 2000-1500 table 1500-1500 are
WORK TO BE DONE IN ACCORDANCE WITH ORDINA OF THE DEPARTMENT OF PUBLIC SERVICE.	ANCE NO. 19-1971	DULY PASSED	BY THE CITY	Y COUNCI	L, AND R
NAME OF CONTRACTOR Decision					

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.