Nº 8984

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED Sec 20 16	IF SO HOW AND LOCATION FROM	•
HOUSE NO. 958	FIRST MANHOLE DOWN STREAM	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT	
	CURB LINE AND DEPTH	
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Mulsule	
SHOW BY DIAGRAM RELATION OF LATERAL TO WAI	LL OF BUILDING SERVED.	
958 bulkis	12 fat from nurth west corner	
Hopet of 6" pipe 10 feet dess 15 feet land and	north west corner	
10 feet des and		
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE	
REMARKS	·	

Nº 8984

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, NIGHT 14		
RECEIVED OF Buse	FEE OF \$25. C		
FOR WHICH PERMISSION IS GRANTED	Bill		
FOR WHICH PERMISSION IS GRANTED	Vacaria.		
	wer on the 65 a T		
OF Ochheil Ca. N. G. ST. T.	PE CF STREET Of Land		
THE PREMISES BEING LOT NO. 13745	, House No		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R OF THE DEPARTMENT OF PUBLIC SERVICE.			
NAME OF CONTRACTOR Malacite	· · · · · · · · · · · · · · · · · · ·		

Wed P.M.

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.