

1-

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 8986

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Closed at Basement

SIGNED _____

[Signature]
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Cut-off
No. 8986 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Sept. 15*

RECEIVED OF

Beaver Engineering Co.

FEE OF \$

5.00

FOR WHICH PERMISSION IS GRANTED

Recess Sewer

Cut-off
TO TAP

Sanitary

SEWER ON THE

South

OF

Summit Ave. S.W.

AVE.

ST. TYPE OF STREET

Half Square

THE PREMISES BEING LOT NO.

1695

HOUSE NO.

570

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Beaver

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**