## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED. Dea	8,1976	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO		
SIZE OF PIPE USED		DISTANCE FROM FIRST MANHOLE DOWN-STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?		
WAS ATTACHED TO MAIN		NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION O	F LATERAL TO WA	LL OF BUILDING SERVED.
		Cosed at Besent
	,	
	<b>,</b>	
SIGNED		FILED AT ENGINEER'S OFFICE

9011

Nº 901

## OFFICE OF THE DIRECTOR OF PUBLIC SER' PERMIT TO TAP SEWER

	MASSILLON, OHIO,	Dec. 3	1
RECEIVED OF Each 306 Year	reting	· · · · · · · · · · · · · · · · · · ·	. FEE OF \$ 5. 0
FOR WHICH PERMISSION IS GRANTED THE STATE OF	saguite Ho	encly	
TOTAL SCREEN		act	
OF Duncan St. S. W. AVE.		Blacktop	
THE PREMISES BEING LOT NO. 406 7	, Hous	SE NO. 10/	7
			` .

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RU OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR 6 act 30

Note: This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.