

N^o 9012FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM*Dec 3*

HOUSE NO. _____

SIZE OF PIPE USED _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

Closed at Basin

SIGNED _____

L
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

CUT-OFF

Nº 9012 ✓

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

Dec. 3

RECEIVED OF

Beaver Excavating Co.

FEE OF

\$5.00

FOR WHICH PERMISSION IS GRANTED

Standard Federal Savings & Loan Assoc.

CUT-OFF

TO TAP

Sanitary

SEWER ON THE

South

OF

Turnout Ave. S.E.

AVE.

ST. TYPE OF STREET

Hard Surface

THE PREMISES BEING LOT NO.

3449

HOUSE NO.

1141

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Beaver

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.