FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

9018

| DATE INSPECTED Dec 23 76 | IF SO HOW AND LOCATION FROM | | |
|--|--|----------------|---|
| HOUSE NO. 2526 | FIRST MANHOLE DOWN STREAM | | |
| HOUSE NO. | | | |
| SIZE OF PIPE USED | DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT | | |
| | CURB LINE AND DEPTH | | |
| WAS LATERAL AT CURB? | | | |
| WAS ATTACHED TO MAIN | NAME OF CONTRACTOR Beaut | | |
| SHOW BY DIAGRAM RELATION OF LATERAL TO WAL | L OF BUILDING SERVED. | | |
| Thet 6 | The Louisi | | • |
| 52 feet 6 | level & | | * |
| aulleured n | E | gen Co | |
| SIGNED Inspector for City | FILED AT ENGINEER'S OFFICE | . - | |
| REMARKS | | | |

Nº 9018

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

| | MASSILLON, OHIO, Dec. 17 |
|---|--------------------------|
| RECEIVED OF Paul Nousack | FEE OF \$ 25. |
| FOR WHICH PERMISSION IS GRANTED Paul King | constit |
| | VER ON THE TOUTH |
| OF Vollywood Au. 71.6. AVE. ST. TYP | E CF STREET CASE Lial |
| THE PREMISES BEING LOT NO. 13674 | |
| WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO | |

NAME OF CONTRACTOR BEAUCE

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.