

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 9020

DATE INSPECTED Feb 11 1937 IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____
HOUSE NO. Whether asked
SIZE OF PIPE USED 4" DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH Repair
WAS LATERAL AT CURB? _____
WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR _____
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

5 feet to 6 inch pipe
[School] Back of school
2 feet deep
34 feet from north East corner
put clean cut in and replaced
4 inch cast iron pipe
5 feet of cast iron pipe

SIGNED J. J. [Signature] Inspector for City FILED AT ENGINEER'S OFFICE

REMARKS Cut up pipe, broke up building repair it and put clean cut in

REPAIR

No 9020

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, FEB. 10, 1971

RECEIVED OF HOLDERBAUM FEE OF \$ 25.

FOR WHICH PERMISSION IS GRANTED REPAIR SANITARY SEWER.

TO TAP SEWER ON THE SOUTH

OF 10TH ST. N.E. AVE. CHIPPY SEAL
ST. TYPE OF STREET

WHITTER SCHOOL
THE PREMISES BEING LOT NO. HOUSE NO.

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR HOLDERBAUM

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.