

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

Nº 9021

DATE INSPECTED

Feb 11 77

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

Reservoir

HOUSE NO.

111

SIZE OF PIPE USED

4 inch

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?


WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

H & W

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

*E S W
N*



*lateral was froze
dug up and
cleaned
1 pipe replaced*

SIGNED

James N. Lewis
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Just behind Curb

Repair

N^o 9021

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO,

Feb. 11

RECEIVED OF

Markowsky

FEE OF

25.

FOR WHICH PERMISSION IS GRANTED

Repair Sanitary Sewer

TO TAP

SEWER ON THE

South

OF

Commonwealth

AVE.

ST. TYPE OF STREET

Brick

THE PREMISES BEING LOT NO.

9692

HOUSE NO.

111

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTIONS OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

H. W. Contractors

Note: This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.