

N^o 9023


FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED Feb 18 77IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAMHOUSE NO. 110.5DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTHSIZE OF PIPE USED 4" diaWAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR J. J. W. Contractor

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



located in right hand
walk in line with N-E corner

75 feet from M.H.
at 1173-276

On 532

SIGNED _____
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS _____

Repair
No 9023

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Feb. 18*

RECEIVED OF *N. A. W. Contractors* FEE OF \$ *25.*

FOR WHICH PERMISSION IS GRANTED *Karvell*

TO TAP *Sanitary* SEWER ON THE *West*

OF *Mundell Ave. W.E.* AVE. *Blanchard*
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *6814*, HOUSE NO. *1105*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *N. A. W.*

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.