

N^o 9026

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

May 23-77

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

7046

SIZE OF PIPE USED

6

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?


yes

WAS ATTACHED TO MAIN

yes

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



REMARKS

Nº 9026

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, March 3

RECEIVED OF Guiny Bros. Inc. FEE OF \$ 25

FOR WHICH PERMISSION IS GRANTED Guiny Bros.

TO TAP Sanitary SEWER ON THE South East

OF Barkhill Dr. N.E. AVE. Chip & Seal

Cedarhill Cr. N.E. 13716 ST. TYPE OF STREET
THE PREMISES BEING LOT NO. 13722 HOUSE NO. 1033 1046

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malanite

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.