Nº 9028

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

~ 11	_ .	
DATE INSPECTED april 20	_ IF SO HOW AND LOCATION FROM	
	FIRST MANHOLE DOWN STREAM	
HOUSE NO. Che Ru Coola	_	
/_	DISTANCE FROM FIRST MANHOLE	<u>.</u>
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? NO	- -	
WAS ATTACHED TO MAIN_ NO	NAME OF CONTRACTOR Mayee	
SHOW BY DIAGRAM RELATION OF LATERAL TO, W		
5 " Program " of Mary bryon	Bulding	
The state of the s	Bfut Stuthon soulf & Grease Dir	
E By	Gnews Dir	cha
78 felt From Mig	Cland out in 10 Beach multi west Corner 10 feet out from Ruleting	ne
	10 Let aut Inon Rulling	
SIGNEDInspector for Cit	ty	

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE PERMIT TO TAP SEWER

•	MASSILLON, OHIO, March 16	
RECEIVED OF Magee Bias	Court. Co.	50 -15-
FOR WHICH PERMISSION IS GRANTED UN Da	Francis	. 1
TO TAP Sanitary	SEWER ON THE South	
OF Chulin Rd-S. W. AVE ST.		
THE PREMISES BEING LOT NO. 1. 287	HOUSE NO. 130/	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND REOF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR 11/ages

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.