

2-
✓

Nº 9034

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

House torn down pluged at basement

SIGNED _____

William Winder
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

3
Cut-off
No 9034

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, April 1
RECEIVED OF East 30 Excavating FEE OF \$ 5.00
FOR WHICH PERMISSION IS GRANTED Dr. Ballinger
CUT-OFF TO TAP Sanitary SEWER ON THE West
OF 1st St. S.E. AVE. Hard surface
ST. TYPE OF STREET
THE PREMISES BEING LOT NO. 2023, HOUSE NO. 419

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTION NO. 19-1971 OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR East 30

Note: This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.