

2-
2

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 9035

DATE INSPECTED _____

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

SIZE OF PIPE USED _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

House to be torn down played at basement

SIGNED _____

Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Cvt. - fb
N^o 9035

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *April 1*

RECEIVED OF

East 306 Leavittsburg

FEE OF \$

5.00

FOR WHICH PERMISSION IS GRANTED

Dr. Ballinger

Cvt-Def
TO TAP

Sanitary

SEWER ON THE

West

OF

1st St. L.C.

AVE.

ST. TYPE OF STREET

Hard Surface

THE PREMISES BEING LOT NO.

2023 B

HOUSE NO.

R-419

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTIONS OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

East 30

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.