## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR 9038 AND SIGNED WHEN RETURNED

DATE INSPECTED JAMES 7	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO.	DIGHT FROM FIRST HANDOLF
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
out 102 thor out	at Basementwell
SIGNED A Y	FILED AT ENGINEER'S OFFICE
Inspector for City	

@. U7-0+

Nº 9038 ✓

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHI	april 4	(
RECEIVED OF BEARLE ENCE FOR WHICH PERMISSION IS GRANTED YMCA- ENT-OFF Sanctary	lavating		FEE OF \$5. U
FOR WHICH PERMISSION IS GRANTED YMCA-	YWCA		
EUT-OFF fanctuy	SEWER ON THE	West	
OF 2 st St. S. S.	'E. T. TYPE (F STREET	Buck	
THE PREMISES BEING LOT NO. 100 H		USE NO. 219	

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RI OF THE DEPARTMENT OF PUBLIC SERVICE.

AME OF CONTRACTOR BEALER

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.