Nº 9041

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED CAPAL 11-77	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN MO	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WAL	L OF BUILDING SERVED.
House	NAME OF CONTRACTOR
15. feet blue wood n	nd cuid
The state of the s	<i>v</i>
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE

Nº 9041

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, APPLICATI	
RECEIVED OF MINE GENESTA	ENSLAGEIL	FEE OF \$ 25
for which permission is granted $\underline{\mathcal{L}(\mathcal{L})}$	HAND HAROGROUT	
TO TAP	SEWER ON THE SOUTH	
OF VALLEYWOOD AVE. N.F.	AVE. ST. TYPE OF STREET CHART SERVE	·
THE PREMISES BEING LOT NO. 13669	, House No2473	
WORK TO BE DONE IN ACCORDANCE WITH ORDINA OF THE DEPARTMENT OF PUBLIC SERVICE.	ANCE NO. 19-1971 DULY PASSED BY THE CITY	COUNCIL, AND RI
NAME OF CONTRACTOR GENERALISTE SLA	MGER	

Note: This permit covers work outside of building only. Any work is walls of building is subject to Massillon Board of Health Regulations.