

N^o 9056

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED

July 28 27

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO.

2033

SIZE OF PIPE USED

6

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

yes


WAS ATTACHED TO MAIN

yes

NAME OF CONTRACTOR

Mulvick

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



20 feet from north east corner

1 foot from east side of porch

15 in line with north west corner
15 feet behind curb

Found by old record

SIGNED

J. H. E.

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

N^o 9056

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, May 17

RECEIVED OF Ernest Rees FEE OF \$ 25.-

FOR WHICH PERMISSION IS GRANTED Ernest Rees

TO TAP Sanitary SEWER ON THE South

OF Ironwood Co. W.C. AVE. Chapman
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 13736, HOUSE NO. 2033

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malavite

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.