№ 9058

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

	F SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO	
SIZE OF PIPE USED OUT	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS ATTACHED TO MAIN 41	is t C
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR.
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	OF BUILDING SERVED.
	OF BUILDING SERVED. John From worth west come found by ald recue 15 hat From worth west come in struct 7 fut beep
	Punt by
118/	Bund ne
SIGNED // Inspector for City	FILED AT ENGINEER'S OFFICE
i inspector for only	

Nº 9058

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO.	cy 18
, フィ	RECEIVED OF EDE Harold Burier	FEE OF \$25
	FOR WHICH PERMISSION IS GRANTED CREST EXCAVO	ting
	TO TAP Santary SEWER ON THE	i El
	OF BUSEL JAVE, M.E. TYPE OF STREET	Chep4 Se
	THE PREMISES BEING LOT NO. 11678 , HOUSE NO.	1229
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED E	THE CITY COUNCIL, AND R

OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR CREST Excavating

Note: This permit covers work outside of bailding only. Any work walls of building is subject to Massillon Board of Health Regulations.

Mus. a. M.