## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

 $N_{\bar{0}}$ 

DATE INSPECTED July 35 27	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
HOUSE NO. 2433	
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO-WAL	
Sofet bearingell and 235	feet in to have that affect of care
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE
REMARKS	

Nº 9076

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

MA	ASSILLON, OHIO,	_ 39
RECEIVED OF Haire Maystane	0	FEE OF \$ 25.
OR WHICH PERMISSION IS GRANTED 11/ac		
O TAP Santary SEWER		
Mindicusalist. M. W. AVE. ST. TYPE		
THE PREMISES BEING LOT NO. 1 47 12	, HOUSE NO	733
VORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 1	9-1971 DULY PASSED BY THE	E CITY COUNCIL, AND R
A. F	•	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.