**Nº** 9084

## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED Land 3 -7	IF SO HOW AND LOCATION FROM Found By all resauch
HOUSE NO. 320	
SIZE OF PIPE USED Court	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	NAME OF CONTRACTOR Placelalan
WAS ATTACHED TO MAIN	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
Manda Manda Sanda Sa	LOF BUILDING SERVED.  Trainal louise 36 feet from Sault went Gener ut blown
30 July 1 30 July 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	
SIGNED 22 of 7	FILED AT ENGINEER'S OFFICE
Inspector for City	

**N**º 9084

## OFFICE OF THE DIRECTOR OF PUBLIC SERVER

	MASSILLON, OHIO, CHIZLET 2, 1
RECEIVED OF Holdesbauer	FEE OF \$
FOR WHICH PERMISSION IS GRANTED 110	Esteun
TO TAR DIG PLATE SEV	VER ON THE COST
OF 22 ND ST N.W. AVE.	PECF STREET Chipy Scal
THE PREMISES BEING LOT NO. 1240, 124	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO	

NAME OF CONTRACTOR HOLDS SAUM

Note: This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.

3