

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

N^o 9090

DATE INSPECTED Aug 15-27

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM 210 feet down stream

HOUSE NO. 1724

SIZE OF PIPE USED 6


DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Mulm

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



W-E
S

SIGNED J. H. S.
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Repair

Nº 9090

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, August 15, 1971

RECEIVED OF John Walker FEE OF \$ 25.

FOR WHICH PERMISSION IS GRANTED Malavite

TO TAP Sanitary SEWER ON THE North

OF Vermont AVE. ST. TYPE OF STREET Chip & Seal

THE PREMISES BEING LOT NO. 6167, HOUSE NO. 1724

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malavite

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.