

N^o 9091



✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED Aug 22-77IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM58 feet up stream from (MID)HOUSE NO. 937DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH9 feet deepSIZE OF PIPE USED 6WAS LATERAL AT CURB? yesWAS ATTACHED TO MAIN no

NAME OF CONTRACTOR

Maher

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

25 feet from south East corner

SIGNED

Inspector for City

7/11/77

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9091

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

15, 1977
la Conate.
77 Oak Hill
Black top
ST
719
77

Malavite Exc.
\$25.00
Eric McPherson

MASSILLON, OHIO, Aug. 15, 1977

RECEIVED OF Sigler Constr. FEE OF \$ 25.

FOR WHICH PERMISSION IS GRANTED City of Massillon Sigler Constr.

TO TAP Sanitars SEWER ON THE West

OF Park Hill Dr. AVE. ST. TYPE OF STREET Ste Chip & Seal

THE PREMISES BEING LOT NO. 13719, HOUSE NO. 977

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Malavite Exc.

Note: This permit covers work outside of building only. Any work i
walls of building is subject to Massillon Board of Health Regulations.