Nº 9093

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM			
HOUSE NO				
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB?	e e e e e e			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
Show by diagram relation of lateral to wall of Building served. Though down play at furnit Mo would				
* * * * * * * * * * * * * * * * * * * *	for the second			
no accord	el	ω .		
// 0	÷			
SIGNED	FUED AT ENGL	NEER'S OFFICE		
SIGNED Inspector for City				
			•	
REMARKS				

Nº 9093

OFFICE OF THE DIRECTOR OF PUBLIC SERVER

	MASSILLON, OHIO,	18 18			
RECEIVED OF Prince of James	Tury	FEE OF 5			
FOR WHICH PERMISSION IS GRANTED Which Permission is granted with the second sec	In Thesital				
FOR WHICH PERMISSION IS GRANTED 221					
CUT-OF Paratray		a T			
τ					
OF	PE OF STREET LA	28235			
THE PREMISES BEING LOT NO. 5361	, HOUSE NO	866			
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RE					
OF THE DEPARTMENT OF PUBLIC SERVICE.					
NAME OF CONTRACTOR		•			

Note: This permit covers work outside of building only. Any work i walls of building is subject to Massillon Board of Health Regulations.