FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 9095 AND SIGNED WHEN RETURNED

DATE INSPECTED Pau 3 - 77	IF SO HOW AND LOCATION FROM 40 fut port
HOUSE NO. 1737	
SIZE OF PIPE USED 6 1	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	Alick
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.	
-7N	Month ret deep at house Wen b feel deep at curf
The state of the s	rientry 26
SIGNED Inspector for City	FILED AT ENGINEER'S OFFICE
inapector for city	
REMARKS	
· · · · · · · · · · · · · · · · · · ·	

№ 9095

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, 30	
RECEIVED OF Daried Select	FEE OF \$	
FOR WHICH PERMISSION IS GRANTED		
TO TAP SEEDS SE		
OF Constity 12., 21. 6 ST. T	4	
THE PREMISES BEING LOT NO. ICL 18 - 11. 118.90 - F.		
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RI		
OF THE DEPARTMENT OF PUBLIC SERVICE.		
NAME OF CONTRACTOR		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.