

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 9100

DATE INSPECTED _____ IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM _____

HOUSE NO. _____

SIZE OF PIPE USED _____ DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH _____

WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____ NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

House torn down plugged at Basement

SIGNED _____

Jim Lewis
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

CUT - OFF

Nº 9100

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, SEP 2

RECEIVED OF

Colony + Sons

FEE OF \$5.00

FOR WHICH PERMISSION IS GRANTED

Mattie Long

CUT - OFF

TO TAP

SAWITARY

SEWER ON THE

West

OF

Dielen G.E.

AVE.

ST. TYPE OF STREET

Chil + Sons

THE PREMISES BEING LOT NO.

9421

HOUSE NO.

321

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR

Colony + Sons

Note: This permit covers work outside of building only. Any work on walls of building is subject to Massillon Board of Health Regulations.