

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

Nº 9108

DATE INSPECTED Sept 7 77

IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM 80 feet up stream

HOUSE NO. 928 allat

DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH 90 feet from rd


SIZE OF PIPE USED 6

WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR _____

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



80 feet sub. hit 90 feet

SIGNED _____ Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Nº 9108

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *Sept. 6*

RECEIVED OF *Frank Coates, Co.*

FEE OF \$ *15.*

FOR WHICH PERMISSION IS GRANTED *John Landray*

TO TAP *Sanitary*

SEWER ON THE *East*

OF *Capital Bldg. W.C.*

AVE.

ST. TYPE OF STREET *347 1/2 S. 1st*

THE PREMISES BEING LOT NO. *13748*

HOUSE NO. *958*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RULES OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *James*

Wed. 9. AM.

Note: This permit covers work outside of building only. Any work inside walls of building is subject to Massillon Board of Health Regulations.