FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED OUT 5-77 IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM CLINICAL ON allucial
HOUSE NO. 1305
DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB? 10 Let bekend
WAS ATTACHED TO MAIN 742 NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED. Rectolespect hourse 19 feet from north East Corner
30 Bird 63 feet 30 Bend
2 g fut dep
SIGNED A LIC 20Th at SW FILED AT ENGINEER'S OFFICE
Inspector for City
REMARKS

N° 9113

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO,	ct. 3
RECEIVED OF Steinhard 6	Leavating	FEE OF \$ 25.
Legge	acil	
TO TAP Samulary SE	WER ON THE THE	et
BU //// / // / / / / / / / / / / / / /	PE OF STREET Chip &	hal
THE PREMISES BEING LOT NO. 13637		305
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO OF THE DEPARTMENT OF PUBLIC SERVICE.	O. 19-1971 DULY PASSED BY T	HE CITY COUNCIL, AND RI
NAME OF CONTRACTOR Steinwach		

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.