

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

N^o 9118

DATE INSPECTED Oct-27-77

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2627

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

SIZE OF PIPE USED 6


WAS LATERAL AT CURB? yes

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Mike Jensen slaps

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



3 feet in From north East corner
6 feet deep
5 feet behind street

E-↑-w
S

old Record good

Rhode Island ne

SIGNED J 14 J

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9118

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, OCT. 27

RECEIVED OF MIKE GERSTENSLAGER FEE OF 25.00

FOR WHICH PERMISSION IS GRANTED MIKE GERSTENSLAGER

TO TAP SANITARY SEWER ON THE ~~RHODE~~ SOUTH ISLAND

OF RHODE ISLAND AVE. CHIP + SEAL
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 4514, HOUSE NO. 2627

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTION NO. 19-1971 OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR MIKE GERSTENSLAGER

Note: This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.