

N^o 9133

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED Dec. 20-77

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 1008

SIZE OF PIPE USED 6

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH



WAS LATERAL AT CURB? no

WAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR Mayer Bros Co

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

9 feet from north west corner



SIGNED

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9133

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, Dec. 14

RECEIVED OF *Mager Bros. Constr. Co.*

FEE OF \$

FOR WHICH PERMISSION IS GRANTED *Italian American Broom Society*

TO TAP *Sanitary* SEWER ON THE *East*

OF *9th St. S.W.* AVE. *Blacktop*
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. *0-1-292*, HOUSE NO. *1008*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTION NO. 10-1971 OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *Mager*

Note: This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.

M. W. Warrington

M. W.