## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 9134 AND SIGNED WHEN RETURNED IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH\_ WAS LATERAL AT CURB? WAS ATTACHED TO MAIN\_\_\_\_\_\_ NAME OF CONTRACTOR. SHOW BY DIAGRAM RELATION OF LATERAL TO WALL GANAGE House 9 Feet IN From south. West Conven Inspector for City WINDSOM

9 Feet Deep

## **№** 9134

## OFFICE OF THE DIRECTOR OF PUBLIC-SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, 15.	15
RECEIVED OF Junipul Great	nating	
FOR WHICH PERMISSION IS GRANTED	ricale fee	
TO TAP Saintant SEW	JER ON THE 6 ac	t-
of Windson Hd. 71.6. AVE. ST. TYP		to
THE PREMISES BEING LOT NO 5446 - 41-494 // .	F439 , HOUSE NO. 1818	
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. OF THE DEPARTMENT OF PUBLIC SERVICE.	. 19-1971 DULY PASSED BY THE CI	TY COUNCIL, AND R
NAME OF CONTRACTOR		

Marie ?

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.