№ 9136

FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

HOUSE NO. 1117 was les ED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH
WAS LATERAL AT CURB?	Dinia
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL	OF-BUILDING SERVED.
ENST CONNER	House 5 2 Fratdeep 5 2 8 28 feetdeep E
"many analysis of the control of the	
SIGNED.	FOUND BYILED AT ENGINEER'S OFFICE
Inspector for City	
• .	

√º 9136

OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, OHIO, Well, 29
es	RECEIVED OF Incam Homes FEE OF \$25.
78	FOR WHICH PERMISSION IS GRANTED DECENTAGE
2	TO TAP Santary, SEWER ON THE West
	OF Wales RATTLE AVE. ST. TYPE OF STREET Hard Surfa
	THE PREMISES BEING LOT NO. 74.79 , HOUSE NO. ///7
	WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R

NAME OF CONTRACTOR HILL DIANA

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.