

N^o 9147

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED


DATE INSPECTED May 13 74IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM0 86 feet to the inHOUSE NO. 2006SIZE OF PIPE USED 6 inDISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTHWAS LATERAL AT CURB? noWAS ATTACHED TO MAIN yes

NAME OF CONTRACTOR

Melvin

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

22 feet from south west
corner



SIGNED

JHR

Inspector for City

FILED AT ENGINEER'S OFFICE

2 300 Bands from main 2 pipe

REMARKS

Nº 9147

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, March 28

RECEIVED OF Guicy Bros. FEE OF \$ 25.

FOR WHICH PERMISSION IS GRANTED Guicy Bros.

TO TAP Sanitary SEWER ON THE North

OF Dakota Co. W.C. AVE. Chippewa
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 13706, HOUSE NO. 2006

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTIONS OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Melanite

Note: This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.