

20-
✓

Nº 9149

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED May 24, 1978

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

HOUSE NO. 2024

SIZE OF PIPE USED

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

WAS LATERAL AT CURB?

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR Malowite


SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

16 feet from
south west corner
10 feet deep at house



tie in 15 feet behind curb
2 feet from south west corner
of porch

N
W E
S



SIGNED _____
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9149

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, March 28

RECEIVED OF Erney Bros. FEE OF \$ 25.

FOR WHICH PERMISSION IS GRANTED Erney Bros.

TO TAP Sanitary SEWER ON THE North

OF Oak Hill Cir. 716 AVE. Chas E. Seal
ST. TYPE OF STREET

THE PREMISES BEING LOT NO. 13708, HOUSE NO. 2024

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTION NO. 19-1971 OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Melanite

Note: This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.