

2nd
twin

Woo

tie in Rec and is connect
9 feet deep in Box 11

Lateral is 5 feet off curb

STOWN NE

4-21-78 - Permit issued
Installed December, 1978 ???



Permit Lost

Inspector went Out 2-13-79
and took down the above information

9152

¹⁶⁻⁵⁰¹
Lot 11942 - 841 Woodview N.E.

30° Bend at house and then pipe to 2.00



40 feet from South

16
32
2

Nº 9152

**FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED**

DATE INSPECTED Dec 12-28

IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAM

At stouch 146 feet

HOUSE NO. 841

DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH

21 feet
in


SIZE OF PIPE USED 6

WAS LATERAL AT CURB? 20 feet behind

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED



SIGNED

Went in at north East corner of porch
Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Stoner

Nº 9152

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, April 21

RECEIVED OF Mike Gentrakovic FEE OF \$ 25.

FOR WHICH PERMISSION IS GRANTED Robert P. His

TO TAP Sanitary SEWER ON THE East West
Woodrow Wilson St.
OF Residence Co. St. AVE. TYPE OF STREET City & Local

THE PREMISES BEING LOT NO. 79308 11942, HOUSE NO. 841

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND RESOLUTION NO. 19-1971 OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR Gentrakovic

Note: This permit covers work outside of building only. Any work inside of building is subject to Massillon Board of Health Regulations.