## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

9156

DATE INSPECTED	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM		
HOUSE NO	DISTANCE FROM FIRST MANHOLE		
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH		
WAS LATERAL AT CURB?	•		
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR		
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.			
RIGNED	FILED AT ENGINEER'S OFFICE		
Inspector for City			
PEMARKS			

0 UT-0FF Nº 9156

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

	MASSILLON, C	оню, <u>/// а.у. 3</u>	
RECEIVED OF CHEWRY &	Lons	FEE OF \$	5. 2
FOR WHICH PERMISSION IS GRANTED 21/a	mici Dine	······································	
FOR WHICH PERMISSION IS GRANTED 1910 FUT. OF F January	SEWER ON THE	Gat	
DF CARLES. VV.			
THE PREMISES BEING LOT NO. $2950$		HOUSE NO. 600	
WORK TO BE DONE IN ACCORDANCE WITH ORD			, AND R
NAME OF CONTRACTOR Clearly	~~~~~		

Note: This permit covers work outside of building only. Any work

walls of building is subject to Massillon Board of Health Regulations.