FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

DATE INSPECTED 2124-18-78 HOUSE NO. 853	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM FULL SI O'COLOR O'			
SIZE OF PIPE USED	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH			
WAS LATERAL AT CURB?	NAME OF CONTRACTOR Mulaul			
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR TO LANGUAGE			
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.				
	Spetgeep bet from must west were			
signed 118	16. The Filed at Engineer's Office			
Inspector for City				

5

Nº 9162 \$

OFFICE OF THE DIRECTOR OF PUBLIC SER' PERMIT TO TAP SEWER

71/21/20

	MASSILLON, O	ню,	(/ :
RECEIVED OF MILENATE	Exercity	<i></i>	FEE OF \$ 25.
FOR WHICH PERMISSION IS GRANTED Haise	u Kujatone	Kanus, Lu	·c.
TO TAP Saintary	SEWER ON THE)/.c.t	
of 16 th 20% 71.8		e de la companya de	
THE PREMISES BEING LOT NO. 51834	•	<i>J</i>	
WORK TO BE DONE IN ACCORDANCE WITH ORD OF THE DEPARTMENT OF PUBLIC SERVICE.	DINANCE NO. 19-1971 DL	JLY PASSED BY THE CITY	COUNCIL, AND RI
NAME OF CONTRACTOR MILLARISTE		- NA UN TR SA PA AF TE	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.