## V FOLLOWING DATA TO BE ANSWERED BY INSPECTOR Nº 9177 AND SIGNED WHEN RETURNED

DATE INSPECTED 6 - 13-78	IF SO HOW AND LOCATION FROM FIRST MANHOLE DOWN STREAM	
HOUSE NO. / 3 3 3		
SIZE OF PIPE USED 6	DISTANCE FROM FIRST MANHOLE DOWN STREAM TO DITCH AT CURB LINE AND DEPTH  CORPORATION  CORPORATIO	
WAS LATERAL AT CURB? 10 feet believed	OA. I.	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR Language Contractor	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	Ponch 17 Rat deep 20 hect in from wart East corner	
	Japatdeep }	
D. T. C.	Workston (A)	
SIGNEDA_R	FILED AT ENGINEER'S OFFICE	
Inspector for City		

## Nº 9177

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

, MA	SSILLON, OHIO, VALUE /5
RECEIVED OF Suntable Of Contract	(Color) FEE OF \$ 25.
FOR WHICH PERMISSION IS GRANTED	- <u>-</u> -
TO TAP Sanctary SEWER	ON THE
of 90 th the Ave.	F STREET
THE PREMISES BEING LOT NO. 136 40	- Para di Para
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19 OF THE DEPARTMENT OF PUBLIC SERVICE.	9-1971 DULY PASSED BY THE CITY COUNCIL, AND RI
NAME OF CONTRACTOR Lainhach	

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.