

N^o 9182


✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED July 12 1909IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAMFound by old recordHOUSE NO. 1809SIZE OF PIPE USED 6DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTHWAS LATERAL AT CURB? about

WAS ATTACHED TO MAIN

NAME OF CONTRACTOR

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.

12 feet from cornerCame out one foot inside
garage floorSIGNED 7/12/09

Inspector for City

FILED AT ENGINEER'S OFFICE

REMARKS

Nº 9182

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *July 10*

st
E
RECEIVED OF *Water Const Co.*

#12 E
FEE OF \$ *2.00*

FOR WHICH PERMISSION IS GRANTED *Water Const Co.*

TO TAP *Sanitary*

SEWER ON THE *South*

OF *Woodward St. SE*

AVE.

ST. TYPE OF STREET *Chippewa St.*

THE PREMISES BEING LOT NO. *1249*

HOUSE NO. *1809*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND F
OF THE DEPARTMENT OF PUBLIC SERVICE.

Co.
NAME OF CONTRACTOR *Water Const Co.*

Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.