

N^o 9185

✓ FOLLOWING DATA TO BE ANSWERED BY INSPECTOR
AND SIGNED WHEN RETURNED

DATE INSPECTED Nov 3 - 78IF SO HOW AND LOCATION FROM
FIRST MANHOLE DOWN STREAMlook on map for lateralHOUSE NO. 1015SIZE OF PIPE USED 6DISTANCE FROM FIRST MANHOLE
DOWN STREAM TO DITCH AT
CURB LINE AND DEPTH


WAS LATERAL AT CURB? _____

WAS ATTACHED TO MAIN _____

NAME OF CONTRACTOR

Glick

SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.



33 feet from north East corner

W
S — N
E

SIGNED _____

Carnation
Inspector for City

FILED AT ENGINEER'S OFFICE _____

REMARKS _____

Keep in office

N^o 9185

OFFICE OF THE DIRECTOR OF PUBLIC SERVICE
PERMIT TO TAP SEWER

MASSILLON, OHIO, *1941*

RECEIVED OF *City of Massillon*

FEE OF \$ *1.00*

FOR WHICH PERMISSION IS GRANTED *for sewer*

TO TAP *lot 10*

SEWER ON THE

OF *Washington*

AVE.

ST. TYPE OF STREET *residential*

THE PREMISES BEING LOT NO. *1001*

, HOUSE NO. *1001*

WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971 DULY PASSED BY THE CITY COUNCIL, AND R
OF THE DEPARTMENT OF PUBLIC SERVICE.

NAME OF CONTRACTOR *City of Massillon*

**Note: This permit covers work outside of building only. Any work
walls of building is subject to Massillon Board of Health Regulations.**