## FOLLOWING DATA TO BE ANSWERED BY INSPECTOR AND SIGNED WHEN RETURNED

Nº

9204

DATE INSPECTED (Quel 4 78	IF SO HOW AND LOCATION FROM Que Go for the FIRST MANHOLE DOWN STREAM	
HOUSE NO	DISTANCE FROM FIRST MANHOLE	
SIZE OF PIPE USED	DOWN STREAM TO DITCH AT CURB LINE AND DEPTH	
WAS LATERAL AT CURB? / Land lifesia	$A = D_{\epsilon}$	
WAS ATTACHED TO MAIN	NAME OF CONTRACTOR MANUELL	
SHOW BY DIAGRAM RELATION OF LATERAL TO WALL OF BUILDING SERVED.		
	20 feet from northeast w	
<del>2</del>   1	to the in ifeet West curb	
90 feet the in I feet West Curb		
SIGNEDInspector for City	1114 M FILED-AT ENGINEER'S OFFICE	

**№** 9204

## OFFICE OF THE DIRECTOR OF PUBLIC SER PERMIT TO TAP SEWER

MASSILLON,	оню, Гер
RECEIVED OF Superty / Live	FEE OF S
	willow, Ohie
TO TAP SEWER ON THE	
OFAVE. OFST. TYPE (F STREET	<i>f</i> =
<i>I</i> ' = =	, HOUSE NO. 1615 114 81
WORK TO BE DONE IN ACCORDANCE WITH ORDINANCE NO. 19-1971	
OF THE DEPARTMENT OF PUBLIC SERVICE.	Haltelann Malanite
NAME OF CONTRACTOR SENTENCE SOUTH	January Maline

Juna. 9-28

Note: This permit covers work outside of building only. Any work walls of building is subject to Massillon Board of Health Regulations.